



Power by **VMS**

## MyVehicle.ie On-Site Vehicle Inspection

Please Note: We don't connect diagnostic equipment to vehicles as part of our inspection.

### CUSTOMER DETAILS

|                      |                     |
|----------------------|---------------------|
| <b>CUSTOMER NAME</b> | Joe Bloggs          |
| <b>EMAIL ADDRESS</b> | joebloggs@gmail.com |
| <b>PHONE</b>         | 087-0000000         |

### VEHICLE INSPECTION DETAILS

|                                   |                                               |
|-----------------------------------|-----------------------------------------------|
| <b>INSPECTION TIME &amp; DATE</b> | 7th December @ 3:00pm                         |
| <b>INSPECTING ENGINEER NAME</b>   | Jason Edgeworth                               |
| <b>GARAGE / SELLER NAME</b>       | Alex (Private Sale)                           |
| <b>INSPECTION ADDRESS</b>         | Waterford Business Park, Cork Road, Waterford |
| <b>PHONE</b>                      | 087-0000000                                   |

### VEHICLE DETAILS

|                                    |                                |
|------------------------------------|--------------------------------|
| <b>REGISTRATION NUMBER</b>         | 12D121212                      |
| <b>CHASSIS NUMBER</b>              | W#####12                       |
| <b>ENGINE NUMBER</b>               | BE12345                        |
| <b>MAKE, MODEL, VERSION</b>        | Ford Focus Ghia 1.6 TDCi 95 PS |
| <b>TRANSMISSION, CC, FUEL TYPE</b> | Manual, 1.6 cc, Diesel         |



Power by **VMS**

## **MyVehicle.ie On-Site Vehicle Inspection**

### **INTERIOR VEHICLE INSPECTION** (Items checked only if accessible from a visual inspection)

- |    |                                 |                    |
|----|---------------------------------|--------------------|
| 1. | Keys operating                  | <b><u>YES</u></b>  |
| 2. | Seating condition & operation   | <b><u>GOOD</u></b> |
| 3. | Roof cloth condition            | <b><u>GOOD</u></b> |
| 4. | Window / glass condition        | <b><u>GOOD</u></b> |
| 5. | Flooring / carpet condition     | <b><u>GOOD</u></b> |
| 6. | Dash & trim condition           | <b><u>GOOD</u></b> |
| 7. | Warning lights on dash          | <b><u>NONE</u></b> |
| 8. | Service book or service history | <b><u>YES</u></b>  |
| 9. | Worn or damaged interior items  | <b><u>NO</u></b>   |

### **SEATBELTS & SRS INSPECTION** (Items checked only if accessible from a visual inspection)

- |     |                                |                    |
|-----|--------------------------------|--------------------|
| 11. | Seatbelt condition & operation | <b><u>GOOD</u></b> |
| 12. | Seatbelt returning             | <b><u>YES</u></b>  |
| 13. | SRS warning lights             | <b><u>YES</u></b>  |
| 14. | ISOfix fitted                  | <b><u>YES</u></b>  |

### **BODYWORK EXTERIOR INSPECTION** (Items checked only if accessible from a visual inspection)

- |     |                                         |                    |
|-----|-----------------------------------------|--------------------|
| 15. | Alignment of exterior panels            | <b><u>GOOD</u></b> |
| 16. | Signs or old damage or poor repairs     | <b><u>NO</u></b>   |
| 17. | Paintwork (colour / lustre / condition) | <b><u>GOOD</u></b> |
| 18. | Visual damage to wings                  | <b><u>NO</u></b>   |
| 19. | Visual damage to doors                  | <b><u>NO</u></b>   |
| 20. | Visual damage to bonnet                 | <b><u>NO</u></b>   |
| 21. | Visual damage to roof / sunroof         | <b><u>NO</u></b>   |



Power by **VMS**

## **MyVehicle.ie On-Site Vehicle Inspection**

|     |                                         |                    |
|-----|-----------------------------------------|--------------------|
| 22. | Visual damage to quarter panel          | <b><u>NO</u></b>   |
| 23. | Visual damage to bumpers                | <b><u>NO</u></b>   |
| 24. | Visual damage to tailgate / boot lid    | <b><u>NO</u></b>   |
| 25. | Visual inspection of body condition     | <b><u>GOOD</u></b> |
| 26. | Visual inspection windscreens / windows | <b><u>GOOD</u></b> |
| 27. | Visual inspection of mirrors            | <b><u>GOOD</u></b> |
| 28. | Doors handles & locks working operating | <b><u>GOOD</u></b> |
| 29. | Aerials / spoilers / spotlights         | <b><u>GOOD</u></b> |

### **REAR LUGGAGE COMPARTMENT INSPECTION** (Items checked only if accessible from a visual inspection)

|     |                                                          |                    |
|-----|----------------------------------------------------------|--------------------|
| 30. | Interior luggage compartment condition                   | <b><u>GOOD</u></b> |
| 31. | Carpet or flooring condition                             | <b><u>GOOD</u></b> |
| 32. | Spare wheel fitted                                       | <b><u>YES</u></b>  |
| 33. | Vehicle Jack, wheel brace, tools, & lock nut             | <b><u>YES</u></b>  |
| 34. | Visual inspection for old damage or poor quality repairs | <b><u>GOOD</u></b> |

### **UNDER-BONNET VEHICLE INSPECTION** (Items checked only if accessible from a visual inspection)

|     |                                                    |                    |
|-----|----------------------------------------------------|--------------------|
| 35. | Transmission fluid levels only (automatic gearbox) | <b><u>NA</u></b>   |
| 36. | Coolant level only                                 | <b><u>OKAY</u></b> |
| 37. | Oil level only                                     | <b><u>OKAY</u></b> |
| 38. | Brake fluid level only                             | <b><u>OKAY</u></b> |
| 39. | Power steering fluid level only                    | <b><u>OKAY</u></b> |
| 40. | Clutch fluid level only                            | <b><u>OKAY</u></b> |
| 41. | Fuel system condition                              | <b><u>OKAY</u></b> |
| 42. | Cooling system condition                           | <b><u>OKAY</u></b> |
| 43. | Visual signs of corrosion or rust under bonnet     | <b><u>OKAY</u></b> |
| 44. | Visual signs or poor quality repairs under bonnet  | <b><u>OKAY</u></b> |
| 45. | Visual cable condition                             | <b><u>OKAY</u></b> |



Power by **VMS**

## **MyVehicle.ie On-Site Vehicle Inspection**

- |     |                                     |                    |
|-----|-------------------------------------|--------------------|
| 46. | Radiator & expansion tank condition | <b><u>OKAY</u></b> |
| 47. | Engine mountings condition          | <b><u>OKAY</u></b> |
| 48. | Battery mountings secure            | <b><u>OKAY</u></b> |
| 49. | Alternator mounting secure          | <b><u>OKAY</u></b> |
| 50. | Visible wiring condition            | <b><u>OKAY</u></b> |

### **WHEELS / TYRES INSPECTION** (Items checked only if accessible from a visual inspection)

- |     |                               |                    |
|-----|-------------------------------|--------------------|
| 51. | Alloys wheels or steel wheels | <b><u>OKAY</u></b> |
| 52. | Spare wheel fitted            | <b><u>YES</u></b>  |
| 53. | Condition of wheels           | <b><u>GOOD</u></b> |
| 54. | R/H/F tyre condition          | <b><u>GOOD</u></b> |
| 55. | L/H/F tyre condition          | <b><u>GOOD</u></b> |
| 56. | L/H/R tyre condition          | <b><u>GOOD</u></b> |
| 57. | R/H/R tyre condition          | <b><u>GOOD</u></b> |
| 58. | Spare tyre condition          | <b><u>GOOD</u></b> |
| 59. | R/H/F tyre thread dept        | <b><u>GOOD</u></b> |
| 60. | L/H/F tyre thread dept        | <b><u>GOOD</u></b> |
| 61. | L/H/R tyre thread dept        | <b><u>GOOD</u></b> |
| 62. | R/H/R tyre thread dept        | <b><u>GOOD</u></b> |
| 63. | Spare tyre thread dept        | <b><u>GOOD</u></b> |

### **VEHICLE BRAKES INSPECTION** (Items checked only if accessible from a visual inspection)

- |     |                                |                    |
|-----|--------------------------------|--------------------|
| 64. | Pedal Rubbers                  | <b><u>GOOD</u></b> |
| 65. | Service brake operation        | <b><u>GOOD</u></b> |
| 66. | Parking brake operation        | <b><u>GOOD</u></b> |
| 67. | Front brake pad visible check  | <b><u>OKAY</u></b> |
| 68. | Front brake disc visible check | <b><u>OKAY</u></b> |
| 69. | Rear brake pad visible check   | <b><u>OKAY</u></b> |



Power by **VMS**

## **MyVehicle.ie On-Site Vehicle Inspection**

70. Rear brake disc visible check **OKAY**

### **STEERING / SUSPENSION INSPECTION** (completed only if a ramp is available at the vehicle's location)

71. Static steering test **OKAY**

72. Power steering pump functioning **OKAY**

### **LIGHTING / ELECTRICS VEHICLE INSPECTION** (Items checked only if accessible from a visual inspection)

73. Front / rear lamps **GOOD**

74. Head light dip beams **OKAY**

75. Head light full beam **OKAY**

76. Headlamps condition **OKAY**

77. Side lights working **YES**

78. Indicators working **YES**

79. Hazard lamps **OKAY**

80. Dash lights **OKAY**

81. Horn **OKAY**

82. Radio **OKAY**

### **UNDERBODY VEHICLE INSPECTION** (completed only if a ramp is available at the vehicle's location)

83. Visual under body condition inspection **GOOD**

84. Visual brake pipes inspection condition **OKAY**

85. Visual inspection of sub-frames condition **OKAY**

86. Visual inspection of jacking points condition **OKAY**

87. Visual inspection of the exhaust system condition **OKAY**

88. Visual inspection under body protection trays condition **OKAY**

89. Visual inspection catalytic converter & visual inspection of DPF **OKAY**



Power by **VMS**

## **MyVehicle.ie On-Site Vehicle Inspection**

### **ROAD TEST**

|      |                                             |                    |
|------|---------------------------------------------|--------------------|
| 90.  | Engine start                                | <b><u>GOOD</u></b> |
| 91.  | Warning lamps on dash                       | <b><u>OKAY</u></b> |
| 92.  | Wipers / washers                            | <b><u>OKAY</u></b> |
| 93.  | Engine Performance                          | <b><u>GOOD</u></b> |
| 94.  | Clutch operation                            | <b><u>OKAY</u></b> |
| 95.  | Audible noise from transmission or flywheel | <b><u>NONE</u></b> |
| 96.  | Gear box operation                          | <b><u>OKAY</u></b> |
| 97.  | Heated windows / mirrors                    | <b><u>OKAY</u></b> |
| 98.  | Steering wheel operation & alignment        | <b><u>OKAY</u></b> |
| 99.  | Brake operation                             | <b><u>GOOD</u></b> |
| 100. | Instruments functioning                     | <b><u>YES</u></b>  |
| 101. | Heating / ventilation                       | <b><u>OKAY</u></b> |

### **MYVEHICLE.IE DECLARATION**

A MyVehicle.ie On-Site Pre-Purchase Inspection includes inspections of a vehicle's interior, engine bay, bodywork, paintwork, underbody (if a ramp is available on-site) and also encompasses a road test of this vehicle. We do not remove parts, connect this vehicle to computers or diagnostics nor do we carry out any type of background or paperwork check of this vehicle.

A MyVehicle inspecting engineer (or its agent acting on its behalf) has carried out on this vehicle is a visual and external inspection and MyVehicle.ie cannot accept responsibility for a failure to identify defects not readily apparent at the time of inspection. No dismantling of any kind has been undertaken.

While every effort has been made to ensure a thorough examination of the paint and bodywork is undertaken, presentation of the vehicle, weather conditions and the location/facilities may have an influence on the outcome of this area of inspection.



## **MyVehicle.ie On-Site Vehicle Inspection**

The odometer reading recorded is taken from the display on the vehicle at the time of inspection unless otherwise stated. Please note that this is not confirmation of the vehicle's covered mileage.

A MyVehicle.ie inspecting engineer has no previous knowledge of this vehicle being involved in a crash, if any bodywork has been carried out or if there has been any major mechanical work been done on this vehicle and our engineer is limited with what they can tell about a vehicle when carrying out our pre-purchase vehicle inspection.

MyVehicle.ie On-site Pre-purchase Vehicle Inspection report under no circumstances guarantees that this vehicle has not been involved in a crash or if there has been any damage repair carried out. This is a visual interior and exterior check and standard mechanical healthcheck without putting the vehicle on a ramp and that only takes into consideration the basic safety and mechanical issues.

MyVehicle.ie do not accept any responsibility for any Mechanical failures, NCT Failures, Damage, Bodywork Repairs, Flood Damage, Write-Off and Mileage Tampering on any vehicle that has had a MyVehicle.ie On-Site Pre-purchase Inspection.

We do recommend that every buyer directly ask the current vehicle owner / seller the following questions and try and get satisfactory answers to these prior to purchasing the vehicle:

Has this vehicle ever been involved in a crash?

Has there ever been any bodywork carried out on this vehicle?

Has this vehicle had any major mechanical work done?

When was the last full service carried out?

If imported vehicle, has the relevant charges (VAT and VRT) been paid?

Is the odometer reading correct?

We also recommend that every buyer purchase our Full Vehicle History and Finance Check Report prior to purchasing a vehicle.

This report may prevent purchasing a vehicle that is: Under an active financial agreement, Written Off, Clocked, etc.



**MyVehicle.ie On-Site Vehicle Inspection**